



Making a "High Notch Skinner". Sam Stoner Jr.


Dab off corners on grinder




Forge steep angle (approx 45°)



Forge radius on upper corner and at same time bring point to center line of bar




desired result



Next, establish blade length


Forge distal taper at this point

Do not thin ricasso




If desired, High Notch can be made at this point

Start at 1800° forge to 1300° Concentrate Blows here



Forge Bevels




this will raise point

lighten Blows as temp. nears 1300°


Do not thin below 1/16 in thickness

Hot cut knife from bar 3 1/2" from ricasso notch.



Forge handle taper over anvil edge.


Forge distal taper length of tang



2

Bring blank to cherry red and clamp edge up in vise. allow 1/2" of point past jaws.

Sight along tang and edge and hammer straight. Tip protrudes enough to top right or left as needed.



Once straight, Bring to just non magnetic (cherry range), air cool to black heat. (1st normalizing)

Reheat to nonmagnetic and air cool to room temp. (2nd normalizing)
This refines grain structure and softens for grinding/drilling.

Next is grinder work...

Grind profile to desired shape




Clean up all edges

Next we must establish flat surfaces...

2nd Grind tang flat on grinder platten

Remove all scale/hammer marks from



Grind Bevels next...



- Important considerations are:
- Don't take grind line too high before heat treat


- Be sure plunge cuts line up and edge is straight & centered two/three/or more pins

Now drill handle pin holes

I use #30 bit for 1/8" & #41 bit for 3/32"

& letter F Bit for 1/4" holes

This give a couple thousandths clearance that is very helpful!



Heat treating: This determines final Potential.

Place knife edge down in clean even fire

Only enough air blast to reach proper temp.

We only need to reach Non magnetic over bottom half of blade

Quench bottom half in light oil

when all color is gone, submerge entirely.



Repeat this process for a total of 2 Cycles.

3

Once cooled to handling temp. we must clean hardened portion and wipe extra oil off knife. Use grinder or sandpaper on hardened area until clean metal surface is bare.

Blade can be placed in oven for 1 1/2 hours at 400° or... use propane torch: Heat spine with tip of flame.



Heat slowly, moving flame along spine only.


Watch for pale yellow color on shiny metal. Color will change fast. When color is dark brown with violet tint quench in water.

Next, finish grinding by taking to final thickness approx. .020 to .025 at edge. Grind all surfaces to at least 220 grit finish.

On slack belt grind convex edge.

220 or 400 grit

Hand polish or buff blade now.




Handles... Trace handle outline on desired material

Cut material being sure to stay approx 1/8" oversized.



Grind both slabs flat.


Clamp one slab to the tang with vise grip and drill using tang as a template



Repeat with opposite side.

Cut pin stock min. 1/8" longer than total handle thickness.

Slide pins through one slab and at least partially into opposite handle slab



Now grind or file top of handle slab so that they are even, finish with 220 or finer

Make a trial fit to be sure everything fits nicely.

Mix epoxy, dip pins in glue and place in one slab. Coat slabs liberally. Clamp tightly. When dry, grind to shape. Radius done with slack belt.

Finish all surfaces to at least 220 grit.

Enjoy your new knife!